

Utility Conflict Report

OWNER	Utility	CPS	Corridor	RIGSBY	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	2074	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Utility Conflict Description	POLE WITHIN PROPOSED SIDEWALK			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE			
LOCATION	Sheet No.	326			
	Station Origin				
	Start Station	660+55.54	End Station		
	Start Offset	10.3	End Offset		
	Latitude	29.398172853	Longitude	-98.435740253999995	
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY COORDINATION IN PROGRESS			
	Comment	INSUFFICIENT CLEARANCE PER PROWAG, 48" CLEARANCE REQUIRED. 39" BACK OF CURB TO FACE OF POLE, 16" POLE DIA, 25" BACK OF POLE TO ROW (BACK OF SIDEWALK)			
Date Collected		8/14/2017 11:29:57 AM	Date Modified		11/9/2017 5:45:01 PM

