

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	RIGSBY	SITE PHOTOS
OWNER	Contact	tact NINA BITTI		.E <b>ID</b> 2093		
0						
<b>GENERAL INFO</b>	Utility		SANITARY SEWER			
	Size and Material		STANDARD MANHOLE, CAST IRON			
	Utility Conflict Description		MANHOLE WITHIN PROPOSED DRIVEWAY, INSIDE ACCESSIBLE ROUTE		40	
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE			
OCATION	Sheet No.	306				
	Station Origin					
	Start Station	584+32.31	End Station	1		
	Start Offset	10.88	End Offset			12
	Latitude	29.398554903	Longitude	-98.4120941	15000002	
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			Ky - A
	Test Hole Depth		N/A			A A
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date					
	<b>Resolution Status</b>		UTILITY COORDINATION IN PROGRESS			
	Comment		ADJUST MANHOLE LID TO PROPOSED GRADE DURING CONSTRUCTION (1" VERTICAL CHANGE ANTICIPATED). EXIST 6" RISER. REMOVE AND REPLACE WITH 2" AND 3" RINGS.			
Date Collected 8/14/2017 6:06:06 PM Date Modified 11/30/2017 8:38:50 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com