

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	RIGSBY	SITE PHOTOS
OWNER	Contact	NINA BITTL	_E	ID	215	
						-
0	Utility		SANITARY SEWER			
INFO	Size and Material		STANDARD MANHOLE, CAST IRON			
<b>GENERAL I</b>	Utility Conflict Description		MANHOLE WITHIN PROPOSED SIDEWALK			- 20 - 20 - 20 - 20 - 20 - 20 - 20 - 20
ЭËN	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE			
Z	Sheet No.	244				
Ō	Station Origin					
AT	Start Station	130+75.50	End Station	1		East End Glass
OCATION	Start Offset	9.08	End Offset			
	Latitude	29.397961555	Longitude	-98.4336605	563999993	271
	Level of Investigation Req'd		NONE			
SUE	Test Hole No		N/A			
S	Test Hole Depth		N/A			
	Recommended Action		MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date					
RESOLUTION	<b>Resolution Status</b>		UTILITY COORDINATION IN PROGRESS			
	Comment		ADJUST MANHOLE LID TO PROPOSED GRADE DURING CONSTRUCTION (1-2" VERTICAL RISE ANTICIPATED)			
$\vdash$	Date Collected	2017 9:37:16 AM				
Date Collected 9/20/2017 5:47:36 PM Date Modified 11/29/2017 9:37:16 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com