

## **Utility Conflict Report**

ШШ	Utility	SAWS		Corridor	RIGSBY		SITE PHOTOS
OWNER	Contact	ANN PECH	E IC	ID	2095		
	Utility		SANITARY SEWER				
INFO	Size and Material		STANDARD MANHOLE, CAST IRON				
NERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station 1	Station 140+60.00					Subject Contract
	Offset						
ŏ	Latitude +	29.398402					
_	Longitude -	98.40662					
	Level of Investigation Req'd		NONE				
SUE	Test Hole No		N/A				
	Test Hole Depth		N/A				
	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
RESOLUTION	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Manhole adjacent to back of sidewalk Unable to open manhole				
	Date Collected 8/14/2017 7:05:35 PM Date Modified 11/28/						018 6:59:12 AM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com