

Utility Conflict Report

IER.	Utility	SAWS		Corridor	RIGSBY	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	2097		
	Utility		SANITARY SEWER				
NFN	Size and Material		STANDARD MANHOLE, CAST IRON				
GENERAL INFO	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
Ш.	Longitudinal or Crossing		CROSSING				
0	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station 140+95.00						
	Offset	t					
	Latitude +29.398394						
_	Longitude -	98.40589					
	Level of Investigation Req'd		NONE				
SUE	Test Hole No		N/A				
••	Test Hole Depth		N/A				
	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
RESOLUTION	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Manhole located partially within existing sidewalk Unable to open manhole				
	Date Collected 8/14/2017 7:23:12 PM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com