

## Utility Conflict Report

|                       |                                     |   |                 |                      |                    |                       |  |
|-----------------------|-------------------------------------|---|-----------------|----------------------|--------------------|-----------------------|--|
| <b>OWNER</b>          | <b>Utility</b>                      | SAWS  | <b>Corridor</b> | NOGALITOS            | <b>SITE PHOTOS</b> |                       |  |
|                       | <b>Contact</b>                      | ANN PECHE   | <b>ID</b>       | 3019                 |                    |                       |  |
| <b>GENERAL INFO</b>   | <b>Utility</b>                      | WATER   |                 |                      |                    |                       |  |
|                       | <b>Size and Material</b>            | STANDARD WATER METER, CAST IRON   |                 |                      |                    |                       |  |
|                       | <b>Accessible Route</b>             | ASSET IS INSIDE ACCESSIBLE ROUTE  |                 |                      |                    |                       |  |
|                       | <b>Longitudinal or Crossing</b>     | CROSSING  |                 |                      |                    |                       |  |
|                       | <b>Placement Relative to ROW</b>    | INSIDE ROW  |                 |                      |                    |                       |  |
| <b>LOCATION</b>       | <b>Sheet No.</b>                    | 113   |                 |                      |                    |                       |  |
|                       | <b>Station</b>                      | 112+52.08   |                 |                      |                    |                       |  |
|                       | <b>Offset</b>                       | -26.63  |                 |                      |                    |                       |  |
|                       | <b>Latitude</b>                     | +29.388861  |                 |                      |                    |                       |  |
|                       | <b>Longitude</b>                    | -98.52189   |                 |                      |                    |                       |  |
| <b>SUE</b>            | <b>Level of Investigation Req'd</b> | NONE  |                 |                      |                    |                       |  |
|                       | <b>Test Hole No</b>                 | N/A   |                 |                      |                    |                       |  |
|                       | <b>Test Hole Depth</b>              | N/A   |                 |                      |                    |                       |  |
| <b>RESOLUTION</b>     | <b>Recommended Action</b>           | MINIMIZE - PROTECT IN PLACE   |                 |                      |                    |                       |  |
|                       | <b>Estimated Resolution Date</b>    |   |                 |                      |                    |                       |  |
|                       | <b>Resolution Status</b>            | UTILITY OWNER INFORMED OF UTILITY   |                 |                      |                    |                       |  |
|                       | <b>Comment</b>                      | Unable to open lid<br>Back of curb to meter = 3'-8"<br>Sidewalk width = 7'-0" |                 |                      |                    |                       |  |
| <b>Date Collected</b> |                                     | 7/2/2018 3:01:01 PM   |                 | <b>Date Modified</b> |                    | 10/12/2018 3:14:06 PM |  |

