

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|---|-----------------|---|--------------------|
| OWNER | Utility | CPS | Corridor | NOGALITOS | SITE PHOTOS |
| | Contact | JAKE MARTINEZ | ID | 3024 | |
| GENERAL INFO | Utility | ELECTRIC | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | | | | |
| | Station | 113+62.02 | | | |
| | Offset | 21.9305 | | | |
| | Latitude | +29.389076 | | | |
| | Longitude | -98.52162 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | |
| | Estimated Resolution Date | 8/13/2018 | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | |
| | Comment | Pole to back of sidewalk = 5'-0" Pole diameter = 12" | | | |
| Date Collected | | 7/2/2018 3:48:11 PM | | Date Modified 8/14/2018 4:38:26 PM | |

