

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	NOGALITOS	SITE PHOTOS	
	Contact	ANN PECH	E	ID	3061		
0	Contact	7.1.11.1.2011	_		0001		
GENERAL INFO	Utility		WATER			K	
	Size and Material		STANDARD WATER VALVE, CAST IRON			S S S S S S S S S S S S S S S S S S S	
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	131					
	Station 1	143+28.33					
	Offset 2	22.15				J. J. M.	
	Latitude -	+29.395559				- 1	
	Longitude	-98.51592					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE				
	Estimated Resolution Date						
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			Y	
	Comment		Lid thickness = 5" Top of valve to surface = 3'-5" Meter to back of curb = 4'-3" Sidewalk width = 4'-6"				
	Date Collected 7/11/2018 10:34:40 AM Date Modified 10/12/2018 3:14:06 PM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800