

Utility Conflict Report

| ER | Utility | CPS | | Corridor | NOGALITOS | | SITE PHOTOS | |
|--------------|---|--------------------|--|----------|-----------|----------|-------------|--|
| OWNER | Contact | JAKE MAR | TINEZ | ID | 3062 | | | |
| GENERAL INFO | Utility | | ELECTRIC | | | \dashv | | |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | E | | |
| | Longitudinal or Crossing | | CROSSING | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | ' | | |
| LOCATION | Sheet No. | 90 | | | | | | |
| | Station | 143+18.49 | | | | | | |
| | Offset 19.85 | | | | | | | |
| | Latitude +29.395656 | | | | | | | |
| | Longitude | ongitude -98.51587 | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | |
| | Test Hole No | | N/A | | | | | |
| | Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | MINIMIZE - PROTECT IN PLACE | | | | | |
| | Estimated Resolution Date | | | | | | | |
| | Resolution Status | | UTILITY OWNER INFORMED OF UTILITY | | | TY | | |
| | Comment | | Pole to back of sidewalk = 3'-9" Pole to back of curb = 1'-8" Sidewalk width (at pole) = 6'-6" Sidewalk width (typical) = 4'-10" | | | | | |
| | Date Collected 7/11/2018 10:42:37 AM Date Modified 9/13/2018 2:01:21 PM | | | | | | | |