

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	NOGALITO	S	SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	3072				
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER METER, CAST IRON						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	129							
	Station	138+87.95					Additional Services  * Tire Rotation  * Wiper Blades  * Let Blades		
	<b>Offset</b> 26.09								
	<b>Latitude</b> +29.394574								
	Longitude	-98.51678							
SUE	Level of Investigation Req'd		NONE			58.			
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
	Comment		Top of meter is 5" below the surface Top of valve is 4 3/4" below the surface Rubber lid thickness = 2" Meter to back of curb = 4'-11" Sidewalk width = 4'-11" Meter located adjacent to building Stair 1 to back of curb = 3'-1" Stair 2 to back of curb = 2'-2" Raise meter enclosure to top of stair						
	Date Collected         7/11/2018 1:51:31 PM         Date Modified         10/12/2018 3:14:06 PM								