

Utility Conflict Report

IER	Utility	SAWS		Corridor	SW MILITARY	,	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID 3100	3100			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRON			N		
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	27						
	Station 5	25+29.76						
	Offset 1	7.1219						
	Latitude +	itude +29.358413						
	Longitude -	98.56180						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A				and the second	
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/14/2018				5 - F.	
	Resolution Status		NO RESOLUTION WAS REQUIRED				1 1 4	
	Comment		Top of valve to surface = 4'-0" Lid thickness = 2" Back of curb to water valve = 2'-3" Back of sidewalk to water valve = 4'-2" Sidewalk width = 7'-0"					
	Date Collected 7/19/2018 11:54:21 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com