


Utility Conflict Report

OWNER	Utility	SAWS		Corridor ID	SW MILITARY 3104	SITE PHOTOS		
	Contact	ANN PECH	E					
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD FIRE HYDRANT					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	32						
	Station 5	541+88.06				Royal Palace		
	Offset 17.94							
	Latitude +29.357880							
	Longitude -98.55659							
SUE	Level of Investigation Req'd		NONE			A COLOR		
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment		Metal wire fen Back of curb to	-				







7/24/2018 8:10:16 AM 12/17/2018 10:17:35 AM **Date Collected Date Modified**