

Utility Conflict Report

| ER. | Utility | SAWS | | Corridor | SW MILITAI | RY | SITE PHOTOS | | |
|---|------------------------------|------------|---|----------|------------|--------|----------------|--|--|
| OWNER | | | г | | | | | | |
| O | Contact | ANN PECH | | ID | 3118 | | | | |
| GENERAL INFO | Utility | | WATER | | | \Box | E | | |
| | Size and Material | | STANDARD FIRE HYDRANT | | | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE RO | | | OUTE | | | |
| | Longitudinal or Crossing | | CROSSING | | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | | |
| LOCATION | Sheet No. | 34 | | | | | | | |
| | Station 5 | 546+91.51 | | | | | | | |
| | Offset 1 | 6.5224 | | | | | | | |
| | Latitude - | -29.357748 | | | | | | | |
| | Longitude | -98.55510 | | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | | |
| | Test Hole No | | N/A | | | | | | |
| | Test Hole Depth | | N/A | | | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | | | |
| | Estimated Resolution Date | | | | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | | |
| | Comment | | Front of sidewalk to hydrant = 3'-2" Sidewalk width = 4'-6" | | | | | | |
| Date Collected 7/24/2018 10:15:21 AM Date Modified 11/28/2018 | | | | | | | 018 6:59:12 AM | | |