

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	BANDERA		SITE PHOTOS		
OWNER	Contact	BILL FEY		ID	3181				
Ó	Contact	BILL! L!			0101		737 4		
GENERAL INFO	Utility		GAS						
	Size and Material		STANDARD GAS VALVE, CAST IRON			N	5		
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU			JTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	292							
	Station	1531+25							
	Offset 4	40							
	Latitude -	+29.530881							
	Longitude	-98.64377							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		10/3/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Front of sidewalk to valve = 1'-6" Fire hydrant to valve = 1'-4 1/4" Top of valve to surface = 3'-10" Lid thickness = 1 1/2"						
<b>Date Collected</b> 8/16/2018 8:41:23 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM							2018 6:59:12 AM		

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800