

## **Utility Conflict Report**

ER	Utility	CPS	C	Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	BILL FEY	II	D	3194			
GENERAL INFO	Utility		GAS					
	Size and Material		STANDARD GAS VALVE, CAST IRON					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			DUTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station							
	Offset							
	<b>Latitude</b> +29.519247							
	Longitude .	-98.63688						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Top of valve to surface = 5'-0" Lid thickness = 1 1/2" Back of curb to valve = 2'-0"					
Date Collected         8/16/2018 1:58:55 PM         Date Modified         11/28/2018 6:59:12 AM							018 6:59:12 AM	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800