

Utility Conflict Report

						_	
JER	Utility	CPS		Corridor	BANDERA		SITE PHOTOS
OWNER	Contact	BILL FEY		ID	3195		
GENERAL INFO	Utility		GAS				
	Size and Material		STANDARD GAS VALVE, CAST IRON			1	
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			DUTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude +29.519261						
	Longitude -	-98.63689					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended A	ction	NO CONFLIC	т			
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Unable to ope Ramp joint to	utility = 2"			
Date Collected 8/16/2018 2:01:24 PM Date Modified 11/28/2018 6:59:12 AM							018 6:59:12 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800