

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	3198		
H	1 14:1:4.		WATER				
GENERAL INFO	Utility		WATER			DOM:	
	Size and Material		STANDARD WATER VALVE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			OUTE	
	Longitudinal or Crossing		CROSSING			Branch Sandaharan	
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station	tation					
	Offset						
	Latitude +29.509607						
	Longitude -98.63007						
SUE	Level of Investigation Req'd		NONE				200
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Edge of parking lot to valve = 10'-5" Lid thickness = 1 1/2" Top of valve to surface = 4'-2 1/2"				
Date Collected 8/16/2018 3:58:46 PM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800