

Utility Conflict Report

ШШ	Utility	SAWS ANN PECHE		Corridor BANDERA ID 3204	BANDERA	SITE PHOTOS	
OWNER	Contact						
GENERAL INFO	Utility		WATER			A	
	Size and Material		STANDARD WATER VALVE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING			The second	
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude +29.507300						
	Longitude -98.62871						
SUE	Level of Investigation Req'd		NONE			the second	
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Group of 3 water valves Unable to open lids Back of driveway to valve = 4'-10" (valve farthest from Bandera) Back of driveway to valve = 7'-2 1/2" (valve closest to Bandera)				
	Date Collected 8/17/2018 8:37:56 AM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com