

## **Utility Conflict Report**

LE R	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	3215				
<b>GENERAL INFO</b>	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			DUTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 2	242							
	Station 1	1406+00							
	Offset 5	55							
	Latitude H	29.500816							
	Longitude	-98.62478					A STATE A STATE OF		
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Unable to open manhole Edge of driveway to manhole = 11'-4" Edge of culvert concrete safety end treatment to manhole = 2'-0"						
Date Collected 8/17/2018 1:28:17 PM Date Modified 12/18/2018 4:53:53 PM							:018 4:53:53 PM		

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com