

Utility Conflict Report

ΠR	Utility	SAWS		Corridor	BANDERA	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID 3220			
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude +29.518944						
	Longitude -98.63672						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A			PAR CONTRACTOR	
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		11/16/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Valve adjacent to culvert concrete safety end treatment Top of valve to surface = 1'-6" Lid thickness = 1 1/2"				
	Date Collected 8/17/2018 3:33:24 PM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com