

Utility Conflict Report

ШШ	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3221			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRON			ON		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUT		OUTE			
	Longitudinal or Crossing		CROSSING					
0	Placement Relative to ROW		INSIDE ROW					
OCATION	Sheet No.							
	Station							
	Offset							
	Latitude +	tude +29.532057						
-	Longitude -98.64521							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
N	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
RESOLUTION	Comment		Edge of culvert to valve = 8 1/2" Unable to open lid Driveway joint to valve = 12'-6"					
	Date Collected 8/17/2018 4:00:52 PM Date Modified 11/28					11/28/2	018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com