

## **Utility Conflict Report**

ER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS
OWNER	Contact	BILL FEY	ID	3243	
<b>GENERAL INFO</b>	Utility		GAS		
	Size and Material		STANDARD GAS VALVE, CAST IRON		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		
	Longitudinal or Crossing		CROSSING		
0	Placement Relative to ROW		INSIDE ROW		
LOCATION	Sheet No.				
	Station				
	Offset				
	Latitude +	29.489935			
	Longitude -	98.61164			
SUE	Level of Investiga	tion Req'd	NONE		
	Test Hole No		N/A		
	Test Hole Depth		N/A		
N	Recommended Action		NO CONFLICT		
	Estimated Resolution Date		9/13/2018		
	Resolution Status		NO RESOLUTION WAS REQUIRED		
RESOLUTION	Comment Top of valve to surface = 2 3/8"   Lid thickness = 1 3/8"				
	Date Collected   8/20/2018 10:23:03 AM   Date Modified   11/28/				2018 6:59:12 AM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com