


## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	NOGALITOS	<b>SITE PHOTOS</b> 
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4039	
<b>GENERAL INFO</b>	<b>Utility</b>	WATER			
	<b>Size and Material</b>	STANDARD WATER METER, STEEL			
	<b>Accessible Route</b>	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	115			
	<b>Station</b>	116+09.44			
	<b>Offset</b>	-26.01			
	<b>Latitude</b>	+29.389651			
	<b>Longitude</b>	-98.52119			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	MINIMIZE - PROTECT IN PLACE			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY OWNER INFORMED OF UTILITY			
	<b>Comment</b>	Top of valve to surface = 4" Sidewalk width = 2'-10"			
<b>Date Collected</b>		7/3/2018 7:58:53 AM		<b>Date Modified</b>	10/12/2018 3:14:06 PM

