

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS
N N	Contact ANN PECHI		E ID 4088				
0							
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON		RON		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		OUTE		
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 1	129					
	Station 5	531+32.20					
	Offset 3	33.0885					4 sug
	Latitude +	-29.358252					NZAZN
	Longitude -	-98.55998					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				and the second
	Test Hole Depth		N/A				N. P.
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/14/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Back of sidewalk to valve = 11'-5" Top of valve to surface = 3'-2.5" Lid thickness = 2"				
	Date Collected	018 6:59:12 AM					

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800