

## **Utility Conflict Report**

Ш	Utility	SAWS		Corridor	SW MILITAF	RY	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	4099		t,	
<b>GENERAL INFO</b>	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		UTE			
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 5	36+88.18						
	Offset 1	7.32						
	Latitude +29.358022							
	Longitude -	-ongitude -98.55820					3 # 3 4	
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		11/21/2018			Tracks		
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Manhole marking: TTSCO Back of curb to manhole = 3'-9" Bottom of cone to surface = 2'-4 1/2" Lid thickness = 1 5/8" Vertical difference between sidewalk and top of manhole = approx 10"					
	Date Collected 7/23/2018 11:06:23 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com