

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	4113			
	Utility		WATER					
GENERAL INFO	Size and Material		STANDARD FIRE HYDRANT					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU		TE			
	Longitudinal or Crossing		CROSSING					
0	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	36						
	Station 5	57+01.25					SAB DIVIN	
	Offset 1	7.3449						
	Latitude +	-29.357455						
	Longitude -	-98.55187						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
•	Test Hole Depth		N/A					
UTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Hydrant to back of curb = 4'-4" Hydrant to fence = 4'-0"					
RESOL			Back of curb to fence = 9'-8"					
	Date Collected 7/27/2018 8:30:09 AM Date Modified 11/28/						2018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com