

Utility Conflict Report

OWNER	Utility	CPS		Corridor	SW MILITAF	RY	SITE PHOTOS	
	Contact	JAKE MAR	TINEZ	ID	4119			
0								
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE .		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	38						
	Station 5	61+98.95						
	Offset 1	5.89						
	Latitude +	-29.357359						
	Longitude	-98.55033						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole to back of Sidewalk widtle Pole to back of Pole to steel presented to the Pole to steel presented to the Pole to steel presented to be pole to back of the Pole t	le ID: LA1785409; 422906 le to back of sidewalk = 3" dewalk width = 3'-0" le to back of curb = 3'-3" le to steel post rail = 3'-2" locate pole to ROW with electric lines ntilevered toward the roadway				
Date Collected 7/27/2018 9:32:34 AM Date Modified 12/18/2018 4:00:09 PM								