

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4131	
<b>GENERAL INFO</b>	<b>Utility</b>	WATER			
	<b>Size and Material</b>	STANDARD WATER VALVE, CAST IRON			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	148			
	<b>Station</b>	636+55.82			
	<b>Offset</b>	18.56			
	<b>Latitude</b>	+29.356503			
	<b>Longitude</b>	-98.52698			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	MINIMIZE - PROTECT IN PLACE			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY OWNER INFORMED OF UTILITY			
	<b>Comment</b>	Valve to back of curb = 3'-9"			
		Sidewalk width = 6'-8"			
		Valve box appears to be abandoned and filled with dirt			
		Top of dirt to surface = 1'-5"			
		Lid thickness = 1 3/4"			
<b>Date Collected</b>		8/1/2018 8:13:23 AM		<b>Date Modified</b>	11/28/2018 6:59:12 AM

