

Utility Conflict Report

| OWNER | Utility | SAWS | | Corridor | SW MILITA | .RY | SITE PHOTOS |
|--|------------------------------|------------|--|-----------------------------|---------------|------|-------------|
| | Contact | ANN PECH | E | ID | 4154 | | |
| GENERAL INFO | Utility | | WATER | | | | |
| | Size and Material | | STANDARD WATER METER, STEEL | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | OUTE | |
| | Longitudinal or Crossing | | CROSSING | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | |
| LOCATION | Sheet No. | 155 | | | | | |
| | Station 6 | 678+90.44 | | | | | - |
| | Offset 23.6279 | | | | | | |
| | Latitude - | +29.356604 | | | | | |
| | Longitude | -98.51368 | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | |
| | Test Hole No | | N/A | | | | |
| | Test Hole Depth | | N/A | | | | |
| RESOLUTION | Recommended Action | | NO CONFLIC | Т | | | |
| | Estimated Resolution Date | | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | 4.0 |
| | Comment | | Top of meter t Lid flange thic Total lid thickr Meter located | kness = 1/2 ness = 1 7/8 |)" -)" | | |
| Date Collected 8/2/2018 8:36:43 AM Date Modified 11/28/2018 6:59:12 AM | | | | | | | |