

Utility Conflict Report

	Jtility	SAWS		Corridor	SW MILITAF	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH	E ID	ID	4215				
ι	Utility		SANITARY SEWER						
INFO S	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
Щ. И	Longitudinal or Crossing		CROSSING						
C) F	Placement Relative to ROW		INSIDE ROW						
- 5	Sheet No. 1	66					Select		
OCATION	Station 72	21+35.45					Hertz		
AT C	Offset 1	7.5675							
۱ o	Latitude +;	29.356545							
r	Longitude -	98.50037							
L	Level of Investigation Req'd		NONE						
I SUE	Test Hole No		N/A						
٦ "	Test Hole Depth		N/A						
F	Recommended Action		NO CONFLICT						
E	Estimated Resolution Date								
ZF	Resolution Status		NO RESOLUTION WAS REQUIRED						
RESOLUTION	Comment		Back of curb to manhole = 4'-8" Sidewalk width = 6'-2" Manhole adjacent to the back of sidewalk Lid flange thickness = 1.5" Overall lid thickness = 3.25" Bottom of cone to surface = 1'-3.5"			alk			
[Date Collected 8/7/2018 8:34:29 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com