



Utility Conflict Report

OWNER	Utility	CPS	Corridor	BANDERA	<div style="border: 1px solid black; padding: 5px; text-align: center;">SITE PHOTOS</div>  		
	Contact	BILL FEY	ID	4580			
GENERAL INFO	Utility	GAS					
	Size and Material	UNKNOWN					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	LONGITUDINAL					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	296					
	Station	1723+20					
	Offset	-20					
	Latitude	+29.485174					
	Longitude	-98.60613					
SUE	Level of Investigation Req'd	QLA					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION					
	Estimated Resolution Date						
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY					
	Comment	811 - Underground gas and electric/cable lines. Request As-builts for line depth verification					
Date Collected		11/20/2018 10:43:52 AM		Date Modified		12/19/2018 11:48:32 AM	