

Utility Conflict Report

ER	Utility	SAWS		Corridor	MILITARY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	7017		
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 2	217					
	Station 1	1099+48.55					
	Offset 2	20.0123					
	Latitude +29.354188					Ø	
	Longitude -98.42262						
SUE	Level of Investigation Req'd		NONE			TA.	
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Water valve in middle of right turn lane Unable to open lid Face of curb to valve = 2'-7" Raise valve cover flush with pavement improvements				
	Date Collected 8/2/2018 1:55:15 PM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com