

Utility Conflict Report

ШШ	Utility	SAWS		Corridor	SW MILITAR	Y	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID 7148	7148			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRC			N		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROU			JTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	72						
	Station 7	54+54.90						
	Offset -2	25.1688						
	_atitude +29.358653						and the second sec	
	Longitude -	98.56203						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Valve to back of wall = 3"					
			Top of valve to surface = 3'-10" Lid thickness = 2"					
	Date Collected 8/6/2018 2:15:15 PM Date Modified 11/28					1/28/2	018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com