

Utility Conflict Report

K	Utility	CPS		Corridor	SW I OOP 41	10	SITE PHOTOS
OWNER	•				SW LOOP 410	'	
O	Contact	JAKE MAR	IINEZ	ID	7500		
	Utility		GAS				
INFO	Size and Material		STANDARD GAS VALVE, CAST IRON				
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
ĮŲ.	Longitudinal or Crossing		CROSSING				
0	Placement Relative to ROW		INSIDE ROW				
z	Sheet No.						
0	Station 2	95+81.53					
LOCATION	Offset -2	20.1091					
	Latitude +	29.377260					
	Longitude -	98.64031					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
ON	Resolution Status		NO RESOLUTION WAS REQUIRED				
RESOLUTION	Comment		Gas valve in concrete riprap Unable to open lid Edge of pavement to front edge of riprap = 6'-3"				
Date Collected 8/14/2018 12:59:14 PM Date Modified 8/14/2018 4:38:26 PM							