

## **Utility Conflict Report**

| ER        | Utility                   | CPS        |   | Corridor  | BANDERA<br>8003 | \ \ | SITE PHOTOS |
|-----------|---------------------------|------------|---|-----------|-----------------|-----|-------------|
| OWNER     | Contact JAKE MART         |            | ΓINIE7  |           |                 |     |             |
| O         | Contact                   | JAKE WAK   | IIIVLZ  | טו        | 6003            |     |             |
|           | Utility                   |            | ELECTRIC  |           |                 |     |             |
| INFO      | Size and Material         |            | STANDARD POWER POLE, TIMBER   |           |                 |     |             |
| GENERAL   | Accessible Route          |            | ASSET IS INSIDE ACCESSIBLE ROUTE  |           |                 |     |             |
| 川川        | Longitudinal or C         | rossing    | CROSSING  |           |                 |     |             |
|           | Placement Relative to ROW |            | INSIDE ROW  |           |                 |     |             |
| OCATION   | Sheet No.                 |            |   |           |                 |     |             |
|           | Station N                 | I/A        |   |           |                 |     |             |
|           | Offset N                  | I/A        |   |           |                 |     |             |
|           | Latitude                  |            |   |           |                 |     |             |
| _         | Longitude                 |            |   |           |                 |     |             |
| SUE       | Level of Investiga        | tion Req'd | NONE  |           |                 |     |             |
|           | Test Hole No              |            | N/A   |           |                 |     |             |
| 0,        | Test Hole Depth           |            | N/A   |           |                 |     |             |
|           | Recommended Ad            | ction      | ACCOMODAT   | E - RELOC | ATION           |     |             |
|           | Estimated Resolu          | tion Date  |   |           |                 |     |             |
| N         | Resolution Status         |            | UTILITY OWNER INFORMED OF UTILITY   |           |                 |     |             |
| RESOLUTIO | Comment                   |            | Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict |           |                 |     |             |
|           | Date Collected            |            | Date Modified 8/17/2018 3:17:37 PM  |           |                 |     |             |