

## **Utility Conflict Report**

ER.	Utility	CPS		Corridor	BANDERA		SITE PHOTOS
Į	_					•	
OWNER	Contact	JAKE MAR	IINEZ	ID	8007		
	Utility		ELECTRIC				
INFO	Size and Material		STANDARD POWER POLE, TIMBER				
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
当							
川川	Longitudinal or C	rossing	CROSSING				
	Placement Relativ	e to ROW	INSIDE ROW				
LOCATION	Sheet No.						
	Station N	/A					
	Offset N	/A					
	Latitude						
-	Longitude						
SUE	Level of Investiga	tion Req'd	NONE				
	Test Hole No		N/A				
0)	Test Hole Depth		N/A				
	Recommended Ad	ction	ACCOMODAT	E - RELOC	ATION		
	Estimated Resolu	tion Date					
TION	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
	Comment		Bandera corrid	dor has not	yet been sur	veyed	
			This record is a placeholder and is not a confirmed utility conflict				
80			committed dam	ty commet			
RESOLI							
	Date Collected Date Modified 8/17/2						)18 3:17:37 PM