

Utility Conflict Report

A R	Utility	CPS		Corridor	RANDER/	Δ	SITE PHOTOS
Ž	•			Corridor	BANDERA		
OWNER	Contact	JAKE MAR	IINEZ	ID	8009		
	Utility		ELECTRIC				
INFO	Size and Material		STANDARD POWER POLE, TIMBER				
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
Image: Control of the point of							
3E	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station N	I/A					
	Offset N	I/A					
00.	Latitude						
	Longitude						
SUE	Level of Investiga	tion Req'd	NONE				
	Test Hole No		N/A				
0,	Test Hole Depth		N/A				
	Recommended Ad	ction	ACCOMODAT	E - RELOC	ATION		
	Estimated Resolu	tion Date					
N O	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
ΙŢ	Comment		Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict				
RESOLI							
М	Date Collected Date Modified 8/17/						18 3:17:37 PM