

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	BANDERA 8010	4	SITE PHOTOS
OWNER	Contact JAKE MART		LINE2				
O	Contact	JAKE WAK	IIIVLZ	טו	6010		
	Utility		ELECTRIC				
INFO	Size and Material		STANDARD POWER POLE, TIMBER				
GENERAL I	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
川川	Longitudinal or C	rossing	CROSSING				
	Placement Relative to ROW		INSIDE ROW				
OCATION	Sheet No.						
	Station N	I/A					
	Offset N	I/A					
	Latitude						
_	Longitude						
SUE	Level of Investiga	tion Req'd	NONE				
	Test Hole No		N/A				
0)	Test Hole Depth		N/A				
	Recommended Ad	ction	ACCOMODAT	E - RELOC	ATION		
	Estimated Resolu	tion Date					
N	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
RESOLUTIO	Comment		Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict				
	Date Collected		<b>Date Modified</b> 8/17/2018 3:17:37 PM				