

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS
Z	Contact ANN PECH			8015			
O	Contact	ANNTECH	L	ID	6015		
	Utility		WATER				
INFO	Size and Material		STANDARD WATER VALVE, CAST IRON				
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
照	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
OCATION	Sheet No.						
	Station N	I/A					
	Offset N	I/A					
	Latitude						
	Longitude						
SUE	Level of Investiga	tion Req'd	NONE				
	Test Hole No		N/A				
O)	Test Hole Depth		N/A				
	Recommended Action		MINIMIZE - PROTECT IN PLACE				
	Estimated Resolution Date						
N	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
RESOLUTIO	Comment		Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict				
	Date Collected		Date Modified 8/17/2018 3:17:37 PM				