

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	7069	
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC			
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	152			
	<b>Station</b>	901+93.75			
	<b>Offset</b>	-15.9			
	<b>Latitude</b>	+29.356853			
	<b>Longitude</b>	-98.51588			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	ACCOMODATE - RELOCATION			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY OWNER INFORMED OF UTILITY			
	<b>Comment</b>	Pole ID: 454612 Pole to back of sidewalk = 3'-9" Back of curb to pole = 2'-7" Pole diameter = 12" Relocate pole to ROW with electric lines cantilevered toward the roadway			
<b>Date Collected</b>		8/3/2018 11:38:21 AM		<b>Date Modified</b> 11/21/2018 2:51:37 PM	

