

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>	
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	4204		
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC				
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER				
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE				
	<b>Longitudinal or Crossing</b>	CROSSING				
	<b>Placement Relative to ROW</b>	INSIDE ROW				
<b>LOCATION</b>	<b>Sheet No.</b>	159				
	<b>Station</b>	717+51.49				
	<b>Offset</b>	15.08				
	<b>Latitude</b>	+29.356577				
	<b>Longitude</b>	-98.50159				
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE				
	<b>Test Hole No</b>	N/A				
	<b>Test Hole Depth</b>	N/A				
<b>RESOLUTION</b>	<b>Recommended Action</b>	ACCOMODATE - RELOCATION				
	<b>Estimated Resolution Date</b>					
	<b>Resolution Status</b>	UTILITY OWNER INFORMED OF UTILITY				
	<b>Comment</b>	Pole to back of curb = 2'-10"				
		Pole to back of sidewalk = 2'- 10 1/2" Sidewalk width = 6'-9" No pole ID TxDOT Traffic Signal Pole to be relocated				
<b>Date Collected</b>		8/6/2018 1:03:44 PM		<b>Date Modified</b> 11/21/2018 2:51:37 PM		

