


## Data Collection Report

|                       |  |   |                       |            |
|-----------------------|--|---|-----------------------|------------|
| <b>GENERAL INFO</b>   | <b>LOCID</b>   | 7   | <b>Latitude</b>       | +26.477353 |
|                       | <b>Highway</b>   | US 83   | <b>Longitude</b>      | -99.047798 |
|                       | <b>County</b>  | Starr   | <b>Element</b>        | Drainage   |
|                       | <b>CSJ</b>   | 0038-06-047   |                       |            |
|                       | <b>Map Link</b>  | <a href="https://maps.google.com/maps?t=h&amp;q=+26.477353,-99.047798">https://maps.google.com/maps?t=h&amp;q=+26.477353,-99.047798</a> |                       |            |
|                       | <b>Field Notes</b>   | 4x4 box- major erosion under mow strip riprap<br>31" guardrail-box is very silted   |                       |            |
| <b>SITE PHOTOS</b>    |  |   |                       |            |
| <b>Photo 1</b>        |  |   |                       |            |
| <b>Date Collected</b> |  | 11/13/2017 2:07:43 PM   | <b>Date Modified</b>  |            |
|                       |  |   | 11/13/2017 2:13:16 PM |            |