PAPE-DAWSON ENGINEERS

# Utility Inventory Report

## GENERAL INFO

| | |
|---|---|
| **ID** | 344 |
| **Corridor** | BS 123B |
| **Latitude** | +29.574584 |
| **Longitude** | -97.964785 |
| **Google Maps Hyperlink** | http://local.google.com/maps?q=+29.574584,-97.964785 |
| **Field Notes** | ROW/Timber |

## UTILITY DETAILS

| | |
|---|---|
| **Utility** | Traffic Signal Pole |
| **Owner** | TXDOT |
| **Type** | Horizontal |

## SITE PHOTOS

**Photo 1** **Photo 2** **Photo 3**

| | | | |
|---|---|---|---|
| **Date Collected** | 12/8/2017 | **Date Modified** | 12/11/2017 12:12:38 |