

Utility Conflict Report

ER	Utility	CPS		Corridor	RIGSBY	SITE PHOTOS
OWNER	Contact	BILL FEY		ID	2088	
	Utility		GAS			
INFO	Size and Material		STANDARD GAS VALVE, CAST IRON			A Carter
GENERAL	Utility Conflict Description		GAS VALVE WITHIN PROPOSED PAVEMENT, OUTSIDE ACCESSIBLE ROUTE			
Ü.	Longitudinal or Crossing		CROSSING			
Ŭ	Placement Relative to ROW		INSIDE			
z	Sheet No.	308				
OCATION	Station Origin					
Ă	Start Station	591+44.13	End Station	I		
Ö	Start Offset	24.3	End Offset			Curette
	Latitude	29.399085039	Longitude	-98.4142414	174999997	A A A A A A A A A A A A A A A A A A A
	Level of Investigation Req'd		NONE			
SUE	Test Hole No		N/A			
<u> </u>	Test Hole Depth		N/A			
	Recommended Action		MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date					
RESOLUTION	Resolution Status		UTILITY COORDINATION IN PROGRESS			
	Comment		ADJUST GAS VALVE LID TO PROPOSED GRADE DURING CONSTRUCTION (1-3" VERTICAL RISE ANTICIPATED)			
	Date Collected 8/14/2017 5:38:38 PM Date Modified 11/9/2					/2017 5:45:01 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com