

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|---|----------------------|---------------------|----------------------|
| OWNER | Utility | SAWS | Corridor | RIGSBY | SITE PHOTOS |
| | Contact | NINA BITTLE | ID | 2095 | |
| GENERAL INFO | Utility | SANITARY SEWER | | | |
| | Size and Material | STANDARD MANHOLE, CAST IRON | | | |
| | Utility Conflict Description | MANHOLE WITHIN PROPOSED SIDEWALK | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE | | | |
| LOCATION | Sheet No. | 277 | | | |
| | Station Origin | | | | |
| | Start Station | 566+84.42 | End Station | | |
| | Start Offset | 25.8 | End Offset | | |
| | Latitude | 29.398402282 | Longitude | -98.406621201999997 | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | MINIMIZE - PROTECT IN PLACE | | | |
| | Estimated Resolution Date | | | | |
| | Resolution Status | UTILITY CONFLICT RESOLVED | | | |
| | Comment | ADJUST MANHOLE LID TO PROPOSED GRADE DURING CONSTRUCTION (1" VERTICAL CHANGE ANTICIPATED) | | | |
| Date Collected | | 8/14/2017 7:05:35 PM | Date Modified | | 8/17/2018 2:20:14 PM |

