

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	TIME WARNER	<b>Corridor</b>	WW WHITE	<b>SITE PHOTOS</b>
	<b>Contact</b>	FRANK CYPRIAN	<b>ID</b>	235	
<b>GENERAL INFO</b>	<b>Utility</b>	COMMUNICATIONS			
	<b>Size and Material</b>	OVERHEAD TELECOMM LINES			
	<b>Utility Conflict Description</b>	LINES TO BE RELOCATED WITH POLE RELOCATION			
	<b>Longitudinal or Crossing</b>	LONGITUDINAL			
	<b>Placement Relative to ROW</b>	INSIDE			
<b>LOCATION</b>	<b>Sheet No.</b>	220			
	<b>Station Origin</b>				
	<b>Start Station</b>	682+18.57	<b>End Station</b>		
	<b>Start Offset</b>	29.73	<b>End Offset</b>		
	<b>Latitude</b>	29.426389405	<b>Longitude</b>	-98.405726917999999	
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	ACCOMODATE - RELOCATION			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY COORDINATION IN PROGRESS			
	<b>Comment</b>	RELOCATE LINES IN CONJUNCTION WITH POWER POLE RELOCATION, SEE CONFLICT ID 114 FOR POLE RELOCATION			
<b>Date Collected</b>		10/4/2017 4:49:14 PM	<b>Date Modified</b>		11/30/2017 8:34:13 AM

