

Utility Conflict Report

ER	Utility	CPS	Corridor WW WHITE	SITE PHOTOS
OWNER	Contact	BILL FEY	ID 253	
Ó				
GENERAL INFO	Utility		GAS	
	Size and Material		STANDARD GAS VALVE, CAST IRON	
	Utility Conflict Description		GAS VALVE WITHIN PROPOSED SIDEWALK	
	Longitudinal or Crossing		CROSSING	
0	Placement Relative to ROW		INSIDE	
-	Sheet No.	197		
LOCATION	Station Origin			
	Start Station	327+21.99	End Station	
0 O	Start Offset	26.53	End Offset	
	Latitude	+29.43564949	Longitude -98.405393353	
SUE	Level of Investigation Req'd		NONE	
	Test Hole No		N/A	
0)	Test Hole Depth		N/A	
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE	
	Estimated Resolution Date			
	Resolution Status		UTILITY CONFLICT RESOLVED	
	Comment		ADJUST GAS VALVE LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)	
	Date Collected	11/27/2017 1	0:28:03 AM Date Modified 8/17/20	018 2:20:33 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com