

Utility Conflict Report

ER	Utility	CPS		Corridor	IH 35	SITE PHOTOS	
OWNER	Contact	BILL FEY		ID	254		
O							
GENERAL INFO	Utility		GAS		GAR-SOT MYLIIN		
	Size and Material		STANDARD GAS VALVE, CAST IRON				
	Utility Conflict Description		GAS VALVE WITHIN PROPOSED SIDEWALK		450/211/000 03/07/40 C46 ft 0.000/27/07/40/27/7/		
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE				
OCATION	Sheet No. 129						
	Station Origin						
	Start Station	233+99.41	End Station			GANAMONO SANAMONO	
	Start Offset	44.46	End Offset				
Ľ	Latitude	29.439033842	Longitude -98	3.47034876	62		
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A			4204 2137091 13707565 640 ft 08.08.2017; 1156:14 PM	
	Test Hole Depth		N/A				
	Recommended Action		MINIMIZE - PROTECT IN PLACE				
RESOLUTION	Estimated Resolution Date						
	Resolution Status		UTILITY CONFLICT RESOLVED		L		
	Comment		ADJUST GAS VALVE LID TO PROPOSED GRADE DURING CONSTRUCTION (1-3" VERTICAL RISE ANTICIPATED)				
Date Collected 11/29/2017 10:49:20 AM Date Modified 8/17/2018 2:20:35 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas Transportation I Water Resources I Land Development I Surveying I Environmental 2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com