

Utility Conflict Report

| 2 | | | | | | SITE PHOTOS |
|------------|------------------------------|--------------|--|------------|----------|-------------|
| Z | Utility | SAWS | | Corridor | WW WHITE | |
| OWNER | Contact | NINA BITTL | .E | ID | 262 | |
| | Utility | | SANITARY SEWER | | | |
| | Size and Material | | | | | |
| INFO | SIZE AIIU WALEITAI | | STANDARD MANHOLE, CAST IRON | | | |
| GENERAL | Utility Conflict Description | | MANHOLE WITHIN PROPOSED SIDEWALK | | | |
| GEN | Longitudinal or Crossing | | CROSSING | | | |
| | Placement Relative to ROW | | INSIDE | | | |
| LOCATION | Sheet No. | 208 | | | | |
| | Station Origin | | | | | |
| | Start Station | 607+75.94 | End Station | | | Seale Rd |
| | Start Offset | 9.55 | End Offset | | | |
| | Latitude | 29.446837152 | Longitude - | 98.4048952 | 77 | |
| SUE | Level of Investigation Req'd | | NONE | | | |
| | Test Hole No | | N/A | | | |
| | Test Hole Depth | | N/A | | | |
| | Recommended Action | | MINIMIZE - PROTECT IN PLACE | | | |
| | Estimated Resolution Date | | | | | |
| RESOLUTION | Resolution Status | | UTILITY CONFLICT RESOLVED | | | |
| | Comment | | ADJUST MANHOLE LID TO PROPOSED GRADE DURING CONSTRUCTION (6-8" VERTICAL RISE ANTICIPATED). ADD 2-3" RISERS. | | | |
| SOLU | Comment | | VERTICAL RISI | | · · | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800