

Utility Conflict Report

ER	Utility	CHARTER		Corridor	SW MILITA	.RY	SITE PHOTOS	
OWNER	Contact	FRANK CY	'RIAN	ID	1028			
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		OVERHEAD TELECOMM LINES					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE		
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 5	34+89.51						
	Offset 1	5.73						
	Latitude +	29.358104						
	Longitude -	98.55887						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT NO RESOLUTION WAS REQUIRED					
	Estimated Resolution Date							
	Resolution Status							
	Comment		Related to utility ID 4095					
	Date Collected	Date Modified 12/18/2			018 4:04:33 PM			

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800